




PH. 07 846 1686 / FX. 07 846 1016  
 PO. BOX 5187 / FRANKTON / HAMILTON / NEW ZEALAND  
 WWW.AVALONLTD.CO.NZ

## GEOTECHNICAL

Tauranga District Council  
 Private bag 12022  
 Tauranga



11 January 2008

For the attention of [REDACTED] s 7(2)(f)(ii)

### **Mauao Slopes; Monitoring Report; 29 November 2007**

Last November we carried out the site work for the ongoing slope inspection/rockfall monitoring program.

Items completed included:

1. Discuss developments with [REDACTED] s 7(2)(f)(ii).
2. Full walkover reviewing slopes from all tracks. Spring flows, slip movements, rockfall evidence, vegetation development etc recorded and photographed.
3. Laser EDM survey carried out at 6 benchmark group locations on; West, North, East Bluffs and Zone 6.
4. Sets of photos from locations A to M around summit for scour monitoring.
5. Visit all 2005 slip sites and check for re-vegetation, stability and tension crack development.
6. Established a set of seven photo monitoring sites around the Oruahine and Waikorere tracks and took initial reference photos.

A summary of findings regarding these items would be:

1. A major rockfall of 30 July has been investigated and reported separately.
2. No other significant events reported to or observed by [REDACTED] s 7(2)(f)(ii).
3. Occasional evidence found of minor rockfall on various track locations.
4. No significant movement on rock bluff benchmarks (within accuracy of measurement). Ongoing settlement of the Zone 6 scaled boulder is slowing and presents no hazard.
5. Scour continuing to develop on steep ground with no vegetation cover.
6. Minor continuing movement and surface ravelling on some of the May 2005 flood event slips.
7. Major dropouts below the 4WD track and wharf access road have been repaired.

The major event since the last monitoring was the failure of a few cubic metres of rock from a location above the Oruahine track on 30 July. Rockfall generated reached the base track and is reported to have narrowly missed a member of the public. See Avalon's report letter dated 17 August 2007. Remaining very marginally stable rock is planned to be removed by blasting in March 2008.

Vegetation continues to re-establish. As previously recognised any weed spraying must be extremely targeted to not leave loose sandy areas prone to scour.

Scour of sand from non-vegetated patches has continued and has been the source of minor rockfall. As reported previously the majority of this will have occurred during inclement weather, at which times there are few persons on the tracks. The majority of the rock likely to fall from these loose surfaces is in the smaller size range (say <150mm).

There has been no wide area loose rock scaling carried out since the initial, 2003 operation and that some slope areas now have significant quantities of loose surface rock.

The general rockfall hazard probably continues to be highest in the northern areas where rock climbers exiting from the top of routes will walk over unstable slopes from which any disturbed rock freefalls onto the Oruahine with no warning. This hazard is exacerbated by the fact that peak climbing activity will coincide with track walking (ie; at weekends during fair weather).

### **Photographs:**

Each monitoring report will present a very small selection of photographs to illustrate the ongoing processes and any new developments (a full photographic record is stored in our files).



*Photograph 1; Repair completed to dropout on lower 4WD track.*



*Photograph 2; Repair completed to dropout wharf access road.*



*Photograph 3; Ongoing scour.*



*Photograph 4; Example of new monitoring point on Waikorere track.*

**Recommendations:**

As per previous reports:

*Although the ongoing rockfall risk to individuals on single visits may be acceptable, a calculated fatality return periods in the order of ten years may be unacceptable.*

*For a person regularly walking the Western Oruahine track (under the rock climbing areas) the rockfall risk may be unacceptably high.*

*The rockfall risk to individual campers appears likely to be acceptable (unless camping on the boundary row for a month or more per year).*

*Some contributing factors to the current level of rockfall risk can possibly be mitigated relatively easily:*

- *It is recommended that rockfall mitigation options be considered for the North West Oruahine Track, the highest risk area. Measures could include access restriction, rock scaling and possibly the consideration of small catch fences.*

January 11, 2008

- *The hazard to the Campground is likely to be most cost effectively mitigated by monitoring and controlled scaling at the rockfall source areas (if and when necessary) although catch fences continue to be an option. The landslip hazard may present a greater overall threat here (than rockfall).*
- *TDC's planting and weed control programme should give priority to establishing grass to help stabilise the loose colluvium.*
- *Public off track access to the steep upper slopes should be prohibited.*
- *Effective track closures must be in place before any TDC staff or contractors access the steep upper slopes off track. Any persons entering these areas must be suitably experienced, competent, trained, equipped, insured etc.*
- *Monitoring and inspection should continue six monthly.*
- *Annual rock scaling is recommended.*

Our next programmed monitoring will be due in the autumn.

We will be in touch regarding the planned blasting works.

Regards

s 7(2)(f)(ii)

For Avalon Industrial Services Ltd.

s 7(2)(f)(ii)

Attached: Site records for Nov 2007 Slope Monitoring.



Avalon Industrial Services Ltd

**Mauao Survey Benchmark Monitoring**

**1-Nov-07**

**Area 1a; "Camp Bluff"**

Installed post blasting, November 2003

1a The Camp Bluff




Distance measurement mm

	Nov-03	Jan-04	Nov-04	Mar-05	Dec-05	Mar-06	Nov-06	Jul-07	Nov-07
3 → 4		5211	5209	5208	not possible	5207	5208	5215	5210
3 → 5		4320	4320	4321	due to	4320	4323	4323	4319
3 → 6		5179	5180	5178	public	5180	5181	5178	5178
4 → 5		2258	2260	2260	below	2260	2260	2258	2259

**Area 2a; "Blasted Column"**

Installed post blasting, November 2003

2a Columns



Distance measurement mm


	Nov-03	Jan-04	Nov-04	Mar-05	Dec-05	Mar-06	Nov-06	Jul-07	Nov-07
8 → 11		7917	7910	7907	not possible	7906	7915	7905	7906
8 → 9			9968	9969	due to	9970	9968	9968	9964
10 → 8			3111	3111	public	3112	3126	3126	3126
10 → 9			11636	11636	below	11633	11635	11634	11634
10 → 11			8325	8325		8325	8325	8325	8320



Blocks above Area 3d; "North Promontary"

Installed March 2003

Above 3d



		Distance measurement mm									
		Mar-03	Nov-03	Jan-04	Nov-04	1/03/2005 *	Dec-05	Mar-06	Nov-06	Jul-07	Nov-07
18	→	5248			5265	5256	5256	5254		5253	5253
20	→	3380			3385	3373	3376	3376	3377	3375	3374
20	→	8038			8065	8050	8056	8050	8053	8053	8054

\* EDM WITH BLOCK (=10)  
# not recorded

Zone 6 Boulder 6b

Installed December 2005

23 (LH outcrop)  
21 (boulder)

		Dec-05	Mar-06	Nov-06	Jul-07	Nov-07
21	→	7560	7590	7615	7663	7639
21	→	5799	5830	5865	5999	5891