

# Mauao Landslips – 29 January 2011

Concept Remedial Options for Large Slips  
affecting the Base Track

Presentation to:  
Mauao Steering Group - 03 March 2011



## Background

- Landslips occurred on 29 January 2011
- Initial Inspection by TCC staff - 30 January 2011
- Inspection by Tonkin & Taylor Ltd - 01 February 2011
- Presentation to Mauao Steering Group - 03 February 2011
- Landslips Classified by size:
  - 22 Minor (<1m<sup>3</sup> debris)
  - 20 Small (1 to 5m<sup>3</sup> debris)
  - 14 Medium (5 to 20m<sup>3</sup> debris)
  - 7 Large (20 to 100m<sup>3</sup> debris)
  - 2 Major (>100m<sup>3</sup> debris)





Tauranga City

# Mauao Base Track Large Landslips



Tonkin & Taylor





Tauranga City


# Mauao Base Track Large Landslips



## Progress to Date

Re-opened 11 February 2011

- Base Track (ocean side)
- Stone Steps
- Lighthouse Track
- Wakorire Track
- Summit Track



## Progress to Date...continued

- Four Wheel Drive Track – re-opened 28 February 2011
- Engineering designs for two Oruahine Track slips completed
  - construction likely to commence 14 March 2011
  - Oruahine Track re-opened by end of March / early April 2011
- Goat Track badly damaged by very large slip - not feasible to repair / re-open in near future (long-term?)





*Tauranga* City



**Tonkin & Taylor**

## **Base Track – Harbour Side**

- Slips to be repaired include:
  - 7 Minor
  - 7 Small
  - 3 Medium
  - 3 Large
  - 1 Major
- Two small slips affect down slope side and require engineering structures to support track
- Minor, small and medium slips all need to be repaired / debris cleared to provide plant access to undertake remedial works on large and major slips





Mauao Base Track Large Landslips



# Base Track Large and Major Slips





*Tauranga City*

## Mauao Base Track Large Landslips



**Tonkin & Taylor**

# Failure Mechanisms

## Slips 3, 4 and 5

### Notes:

- Head scarps are up to 12m high, 16m wide with debris run out distances >100m, debris volumes >200m<sup>3</sup>.
- There are similar size historic slips all around the base of the Mauao – these are nothing unusual





Tauranga City



Tonkin & Taylor

## Remedial Options – Slips 3, 4 and 5

- General Philosophy
  - Ongoing regression of recent (and historic) slips during prolonged and/or intense rainfall events is inevitable
  - Major engineering works required to prevent this – very expensive and major impact on Mauao environment
  - Historic equivalent slips which did not reactivate during recent storm are equally likely to fail in the future
  - Main focus is to keep Mauao accessible and safe to visitors
  - Major slips only likely to occur during / following large rainfall events – temporary track / Mauao closure may be considered during such events?





Tauranga City



Tonkin & Taylor

## Remedial Options – Slips 3 and 4

- Track largely undamaged
- Clear debris from slips, track and foreshore (vegetation, incl. unstable trees?)
- Line scour channels with boulders from slip debris
- Hydroseed and planting on slip scars to reduce visual impact
- Reinstate track and stormwater control
- Include erosion protection measures to reduce risk of future damage to track
- Fence off head scarps or include warning signs where readily accessible to visitors
- Accept risk of future regression of slips and associated damage to Mauao and tracks





Tauranga City

## Mauao Base Track Large Landslips



Tonkin & Taylor

### **Remedial Options – Slips 3 and 4...continued**

- Reduce potential impact of future land slips
    - Include a debris barrier (rock/soil bund or timber posts) with stormwater control
  - Cross section of Slip 3 showing debris bund / timber poles with vegetation
- 
- Reduce likelihood of further significant slope failures
  - Cross section of Slip 3 showing head scarp regraded to 1V:2H and removal of trees?





Tauranga City



Tonkin & Taylor

## Remedial Options – Slip 5

- Track badly damaged
- Reinstatement of track requires significant engineering works:
  - Retaining structure to support track – down slope side high (7-8m), steep and unstable
    - Concrete crib wall
    - Gabion wall
    - Anchored timber wall
    - MassBloc wall, rock protection
- Cross section through Base Track showing crib wall option





Tauranga City

## Mauao Base Track Large Landslips



### Remedial Options – Slip 5

- Trimming back slope difficult (access), destructive (large number of mature trees)
- Allow future failures to occur but reduce risk to track / visitors

#### Footbridge

Plan view of footbridge  
possible locations

#### Concrete culvert

Cross section of track  
showing outfall





Tauranga City

# Mauao Base Track Large Landslips



Tonkin & Taylor





Tauranga City

# Mauao Base Track Large Landslips



Tonkin & Taylor

## Remedial Options – Slip 5...continued

Option	Advantages	Constraints
Footbridge	<ul style="list-style-type: none"> <li>• High level of safety</li> <li>• Built off site – short timeframe</li> <li>• Minimal works to slip required</li> <li>• Less disturbance to natural system</li> <li>• Feature / Aesthetic</li> <li>• Education</li> <li>• Re-use boulders to line channel</li> </ul>	<ul style="list-style-type: none"> <li>• High Cost</li> <li>• Foundation construction</li> <li>• Future maintenance / inspection costs</li> <li>• Aesthetic</li> </ul>
Culvert	<ul style="list-style-type: none"> <li>• Reduced risk to users</li> <li>• Minimal works to slip required</li> <li>• Less disturbance to natural system</li> <li>• Minimal maintenance</li> <li>• Availability of existing culvert(s)?</li> </ul>	<ul style="list-style-type: none"> <li>• High Cost</li> <li>• Construction of gabion walls or similar to support track either side of culvert</li> <li>• Rock protection below to dissipate stormwater runoff</li> <li>• Future maintenance – debris clearance</li> <li>• Aesthetic</li> <li>• Requires hand rail</li> </ul>
Retaining Structure	<ul style="list-style-type: none"> <li>• Minimal maintenance</li> </ul>	<ul style="list-style-type: none"> <li>• High Cost</li> <li>• Safety – doesn't reduce potential risk from future slips</li> <li>• Import of materials to site</li> <li>• Requires hand rail</li> </ul>





Tauranga City

## Mauao Base Track Large Landslips



Tonkin & Taylor

### Slip 6

- Loss of surface material from existing slip – 24m high, very steep (50-60°), 12m wide
- Immediately adjacent to track, but track not badly damaged
- Remedial options
- To achieve an equivalent level of safety as prior to 29 January 2011
  - Minor works including scaling of slip face, debris clearance, track reinstatement, hydroseed to reduce visual impact
  - Can be completed quickly to re-open further section of Base Track to Slip 5

