

Tauranga City Council

Private Bag 12022  
Tauranga Mail Centre  
Tauranga 3143

**Consent Number:** 63791.0.01-CC+

**Inspection Number:** 496404

**Expiry Date:** 31-Oct-2041

**Date of Inspection:** 28-Apr-2025

**Time of Inspection:** 1:00 pm

**Consent Holder(s):** Tauranga City Council

**Site Address(es) :** Pilot Quay Pilot Bay side of Mauao Mount Maunganui

**Purpose :** Erect a Rock Revetment Structure in, on, under, or over the Foreshore and/or Seabed of Tauranga Harbour

**Contact Person During Inspection :**

**Position:**

**Reason for Inspection :**

**Level of Compliance :** Complying

**Comments / Actions Required :**

On the 28th of April 2025 this field sheet was completed after conducting an onsite visit with consent holder to discuss mitigation repairs noted in the previous inspection done on the 31st of March 2025.

Displacement and dislodging of rocks from rock revetment has potentially rendered the rock revetment as less effective in protecting against erosion and scour.

Consent holder is planning staged maintenance works to reinstate the rock revetment to a stable effective erosion protection structure.

s 7(2)(f)(ii)

**Disclaimer:** This report is not intended to be a full review of all compliance issues associated with this consent, nor is it intended to supersede or nullify any conditions of the relevant consent(s)

Bay of Plenty Regional Council has a policy of recovering costs associated with resolving non-compliance issues. These costs may include staff time, mileage, analytical fees and any other material expenses.