



AVALON


// ROPE ACCESS SERVICES

PH. 07 846 1686 / FX. 07 846 1016

PO. BOX 5187 / FRANKTON / HAMILTON / NEW ZEALAND

WWW.AVALONLTD.CO.NZ

NEWSLETTER JUNE 08




Irrelevant

RECENT WORKS

// MT MAUNGANUI REVISITED

A natural rockfall recently resulted in a 'near miss' for walkers on the base track. Neil was called in and located the source of the rockfall, where he found a column of rock showing signs of imminent further failures. Working closely with mauao's ranger Mark Ray and after escorting iwi on a site visit, plans were made to move the rock.

After extensive planning and with public safety ensured, the blast gave the result desired, a push to trigger the rockfall.



Before (left) and after.



Staff chased down the loose rock remains to ensure the safety of people using the track below.



Irrelevant

Irrelevant

Irrelevant

Irrelevant