

These first two show parts of the track before any work was done. Some of these rocks came down in the flood and some in the "scaling" done immediately after the floods, by Avalon abseilers.



The following ones are taken today and show the new works and the repairs

From the bottom of the track going up to the 4WD
These first two are new steps where the track was severely washed out



These next two are in the middle of the track and are repairs



These two are a whole new structure where the track had been washed out. The distance between the bottom of the track and the seat itself was almost one metre.



This next one has had extensive (all new) work and is where the 4WD track meets the Oruahine track.

